



# Course Assessment Report - 4 Column

## Great Basin College

### Courses (CTE) - Welding

Course Outcomes 1 and ctu.unitid = 703	Means of Assessment & Criteria / Tasks	Results	Action & Follow-Up
<p>WELD 105 - Draw/Weld Symbol Int - Line Types used on Prints - Students were given homework assignments on Line Types used on Prints after lectures were given on the same information.</p> <p><b>Next Assessment:</b> 2019-2020</p> <p><b>Start Date:</b> 08/03/2015</p> <p><b>Course Outcome Status:</b> Active</p>	<p><b>Assessment Measure:</b> The methods used to assess the Line Types outcomes was the overall grade for the assignments that the students earned.</p> <p><b>Assessment Measure Category:</b> Assignment - Lab</p> <p><b>Criterion:</b> Students that received a passing grade of 70% or higher have achieved these goals.</p>	<p>08/04/2015 - The students that received the lower grades had problems with attendance and or did not complete all of their homework assignments.</p> <p><b>Criterion Met:</b> Yes</p> <p><b>Reporting Period:</b> 2014-2015</p>	<p>08/04/2015 - 1 Reinforce to the students how important it is to attend all class meetings.</p> <p>2 Reinforce how important it is for the students to complete their homework assignments.</p> <p>3 Encourage students in staying focused on their assignments.</p>
<p>WELD 105 - Draw/Weld Symbol Int - Parts of a Print - Students were given homework assignments on Parts of a Print after lectures were given on the same information.</p> <p><b>Next Assessment:</b> 2019-2020</p> <p><b>Start Date:</b> 08/03/2015</p> <p><b>Course Outcome Status:</b> Active</p>	<p><b>Assessment Measure:</b> The methods used to assess the Parts of a Print outcomes was the overall grade for the assignments that the students earned.</p> <p><b>Assessment Measure Category:</b> Assignment - Lab</p> <p><b>Criterion:</b> Students that received a passing grade of 70% or higher have achieved these goals.</p>	<p>08/04/2015 - The students that received the lower grades had problems with attendance and or did not complete all of their homework assignments.</p> <p><b>Criterion Met:</b> Yes</p> <p><b>Reporting Period:</b> 2014-2015</p>	<p>08/04/2015 - 1 Reinforce to the students how important it is to attend all class meetings.</p> <p>2 Reinforce how important it is for the students to complete their homework assignments.</p> <p>3 Encourage students in staying focused on their assignments.</p>
<p>WELD 105 - Draw/Weld Symbol Int - Welding Symbols - Students were given homework assignments on Welding Symbols used on prints after lectures were given on the same information.</p> <p><b>Next Assessment:</b> 2019-2020</p> <p><b>Start Date:</b> 08/03/2015</p> <p><b>Course Outcome Status:</b> Active</p>	<p><b>Assessment Measure:</b> The methods used to assess the Welding Symbol outcomes was the overall grade for the assignments that the students earned.</p> <p><b>Assessment Measure Category:</b> Assignment - Lab</p> <p><b>Criterion:</b> Students that received a passing grade of 70% or higher have achieved these goals.</p>	<p>08/04/2015 - The students that received the lower grades had problems with attendance and or did not complete all of their homework assignments.</p> <p><b>Criterion Met:</b> Yes</p> <p><b>Reporting Period:</b> 2014-2015</p>	<p>08/04/2015 - 1 Reinforce to the students how important it is to attend all class meetings.</p> <p>2 Reinforce how important it is for the students to complete their homework assignments.</p> <p>3 Encourage students in staying focused on their assignments.</p>